

AMENDMENT TO DRAWINGS (FIG. 8)

Reference Number "95"

In the original Fig. 8, Reference Number "95" incorrectly marked the wrong structure in Fig. 8. As shown in the Annotated Marked-Up Diagram for Fig. 8, the applicant has redrawn Ref. No. "95" to properly indicate the first inner casing surface 95. The proper antecedent basis for this amendment is found in the Specification, page 8, lines 7-10, and Fig. 3. This was an inadvertent error by the applicant, and this amendment was not made in response to any action by the Examiner. No new matter has been added.


Reference Number "105"

In the original Fig. 8, Reference Number "105" incorrectly marked the wrong structure in Fig. 8. As shown in the Annotated Marked-Up Diagram for Fig. 8, the applicant has redrawn Ref. No. "105" to properly indicate the third inner casing surface 105. The proper antecedent basis for this amendment is found in the Specification, page 8, lines 7-10, and Fig. 3. This was an inadvertent error by the applicant, and this amendment was not made in response to any action by the Examiner. No new matter has been added, and the applicant respectfully requests consideration.

Respectfully Submitted,

LAW OFFICE OF DAVID HONG

By



David Hong (Reg. No. 45,704)

Dated: May 21, 2004